




PIPE SCHEDULE AND SPECIFICATION



NOTE *
WELDING PROCEDURES TO FOLLOW HIGHLAND REFRIGERATION WELDING PROCEDURES.
- NO BACKING RINGS.
- NO SOCKET WELDINGS.
- T.I.G. WELDING ONLY.

3 PHASE, 480 VOLT, 60 HZ
CONTROL VOLTAGE: 1 PHASE, 120 VOLT, 60 HZ

APPROXIMATELY 600LBS R-507 CHARGE

					 HIGHLAND REFRIGERATION		4250 24th AVE WEST SEATTLE, WA 98199, USA PHONE: (206)213-0040		DESIGNED:
					CLIENT: Resonate				DRAWN:
					TITLE: Heating / Cooling Skid				APPROVED:
									DWG. NO:
									SCALE: